

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,265,748 B2
APPLICATION NO. : 10/733,872
ISSUE DATE : September 4, 2007
INVENTOR(S) : Ryyanen
TITLE : METHOD AND DEVICE FOR DETECTING TOUCH PAD INPUT

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

1. In column 8, line 54, claim 5, line 7, "tat" should be --that--.
2. In column 9, line 41, claim 6, line 39, "Intensity", should be --intensity--.
3. In column 10, line 36, claim 17, line 1, "claim 8" should be --claim 6--.

Patent No. 7,265,748 B2

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Kenneth Q. Lao
Ware, Fressola, Van Der Sluys & Adolphson LLP
755 Main Street, P.O. Box 224
Monroe, Connecticut 06468

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. **SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**